ARICH										
	BRAZOSPORT ISD BOND 2012 As of 8/31/2018									
Facility Impacted	Bond Item	Useful Life	Department	Purchasing Method	Original Budget	Safety & Security (7.3.18)	Amended Budget	Actual Costs 8/31/18	Balance Status	Notes (Item Details)
Instru	uctional Resources/Classroom Technology								Phase 1, Complete, Phase 2 Complete, 1 to 1 grades 5-12,	Provide campuses with sets of tablets and netbooks to be used in the classrooms. This will increase student
Entire District Entire District Entire District	Mobile Computing Devices for Students Interactive Whiteboards Interactive Electronic Learning Table	7 7 7	Curriculum Curriculum Curriculum	Coop/Bid Bid Bid	5,250,000 2,608,800 720,000	(108,756.00)	4,941,170 948,632 489,231	4,941,170 948,632 489,231	- Moved to Computer for Students and Staff Line 0 Complete, Obsolecence remaining - Complete	access to technology and prepare campuses to move to online textbooks
Entire District Entire District Entire District	Interactive Electronic Learning Slates TCI History Alive TI-NSPIRE Touch Pad	7 n/a 7	Curriculum Curriculum Curriculum	Bid n/a Bid	279,200 781,529 427,372	(987)	279,200 - 512,710	179,775 512,710	99,425 Complete, Obsolecence remaining - Removed due to alternative funding with IMA (0) Complete	
Entire District Entire District	Digital Globes, Atlas, and Map TI-NSPIRE Navigator	n/a 7	Curriculum Curriculum	n/a Bid	155,351 93,695		93,861	93,861	Removed due to alternative funding with IMA (0) Complete	
Entire District Entire District	Microscopes for Int., Middle, and H.S. Dictionaries	7	Curriculum Curriculum	Quote Quote	26,400 23,732	-14700 -3401	11,700 20,331	11,700 20,331	Complete, Remaining balance for refresh Complete, Remaining balance for refresh	
Entire District Entire District	Dissecting Scopes Electrophoresis lab apparatus with power supply	7	Curriculum Curriculum	Quote Quote	9,636 8,800	-911 -2759	8,725 6,041	8,725 6,041	- Complete, Remaining balance for refresh 0 Complete, Remaining balance for refresh	
Entire District Entire District	Digital Cameras - K-12 Global Positioning System for Science	7	Curriculum Curriculum	Quote Quote	5,750 4,800	-2535 -913	3,215 3,887	3,215 3,887	Complete, Remaining balance for refresh Complete, Remaining balance for breakage	
Entire District Entire District	TI 84 Calculators Classroom Projection Devices	7	Curriculum Curriculum	Quote Quote	4,500 1,200,000	(1,713)	40,273 1,200,000	40,273 1,169,086	0 Complete 30,914 Completed, balance for replacements	Replacement of existing projectors, and installation of new devices to standardize for all BISD classrooms
Media Center (Old LJI)	Training center fixtures for Staff Development Classes at Media Center	7-20	Curriculum	Bid	500,000		396,187	396,187	(0) Complete	Lack of space and furnishings to allow training for all Brazosport I.S.D. staff.
Austin, Brannen, Ney, Polk, Roberts, Lanier,	Replace Chalkboards with Dual Purpose									Replace existing chalkboard with whiteboards to serve a dual purpose writing board and projector screen
Rasco, Bport, Bwood	Whiteboard/Projector Screens	15	Curriculum	Соор	180,000		150,567	150,567	1 Complete	throughout the district
Bport Austin, Beutel, Brannen, Fleming, Griffith, Long, Ney, Ogg, Polk, Roberts,	Welding and Agriculture Shop Upgrades	20	Curriculum		130,000	(5,486)	423,730	423,730	0 Complete	Upgrading the current ventilation and fume control system in the Welding and Agriculture facilities at BPort High would provide a safer place for all students to learn the art of welding.
Velasco	HATCH TEACH Learning System	10	Curriculum	n/a	78,165		-	-	Not pursuing initiative due to pursuing an alternative table - with software included	Pre-K has state guidelines that were approved by the Commissioner of Education in 2008 which provides opportunities for Pre-Kindergarten who have been identified as having high-risk factors. Upgrading the current Family and Consumer Sciences cooking lab into a Hospitality Services - Culinary Arts/ Nutrition Lab which equalizes program offerings and gives students learn the hands on skills necessary to work in
Bwood	Culinary/ Nutrition Lab Sub-total Instructional Resources/Classroom Tec	20 hnology	Curriculum		62,000 12,549,730	(142,161)	91,026 - 9,620,486	91,026 9,490,147	0 Complete 130,339	the Hospitality Industry.
	Technology									
Entire District	Computers for Student Labs and Staff	7	Technology	Bid	3,500,000		5,953,830	5,432,620	521,210 Complete, Obsolesence Remaining, Extend program	Replace existing student lab desktops and Staff workstations (old and out of warranty, cannot support newer software and instructional initiatives)
Entire District Entire District	Wired Network Infrastructure Upgrade Wireless Infrastructure Upgrade	7	Technology	Bid	3,200,000 1,250,000		2,360,121	2,345,782	14,339 Complete, Obsolescence pending 41,904 Complete, Obsolescence pending	Replace old network hardware (end of life, no warranty available) Provide necessary wireless bandwidth to support mobile wireless and electronic textbook mandate
Entire District	Wireless Infrastructure Upgrade - ERATE	7	Technology Technology	Bid Bid	-		896,659 1,551,791	854,755 1,546,251	5,540 Complete	Supplemental ERATE funding received for wireless initiative
Entire District	IP Telephone System Upgrade	7	Technology	Bid	1,100,000	232,565	1,232,565	992,414	240,151 Substantially Complete	Replace old phones and upgrade servers/software, end of life/service Replace Comcast links with district owned connections where possible, to minimize ongoing leasing costs with
Entire District Entire District	Partial Fiber/Wireless Build out Software Purchases/Updates	7	Technology Technology	Bid Coop/Quotes	900,000 420,000	60245	483,158 480,245	398,782 434,450	84,376 Phase 1 Bid, Complete 45,795 In progress	Comcast Software purchases/updates to enhance instruction and classroom management, and save on energy costs
Entire District	Standardized Network Printers	5	Technology	Bid	300,000	00240	300,000	171,120	128,880 Complete, Obsolesence Pending	200 monochrome laser jet network printers, to replace old out of warranty printers
Technology Svcs.	Server Virtualization	7	Technology	Bid	225,000		225,000	219,474	5,526 Complete	Effort to reduce long term server costs, and provide better server resource management, also provides energy savings
Entire District	Battery Backups (UPS Devices) Sub-total Technology	5	Technology	Coop/Quotes	125,000 11,020,000	292,810	125,000 - 13,608,369	105,458 12,501,105	19,542 Complete, Obsolesence Pending 1,107,264	District wide replacement of out of warranty and non functioning network closet battery backups
	Renovation									
		6 yr. rotation								The District has not had funding to replace flooring on a routine basis, thus creating campuses with extreme
Entire District Rasco	Carpet rehabilitation program Replace carpet throughout building.	cycle 15	Maintenance Maintenance	Bid Bid	345,000 160,000		493,050 159,605	490,311 159,605	2,739 In Progress 0 Complete	carpeting needs. This funding would provide 6 years worth of routine replacement assuming a 20 year rotation. Carpet in all classrooms and offices are in very poor condition
Griffith	Replace flooring throughout building.	15	Maintenance	Bid	150,000		188,386	188,386	- Complete	Original to building; in need of replacement
Bwood	Replace gym floor.	25	Maintenance	Coop/ Emergency	100,000	19,275	127,125	127,625	(500) Complete	Floor is severely warped due to roof leaks. (CBOC reallocation for training room asbestos abatement/replacement)
Fleming	Replace carpet in all classrooms.	15	Maintenance	Bid	115,000		6,873	6,873	0 Complete	Carpet is worn due to age and high traffic and therefore in need of replacement. Most of the carpet in the building is in good condition however various classrooms have been identified as in need
FIS	Replace carpet in identified classrooms.	15	Maintenance	Bid	35,000		31,537	31,537	0 Complete	of new carpet due to excessive wear due to traffic and age. Most of the carpet in the building is in good condition however various classrooms have been identified as in need
Ogg Lanier	Replace carpet in identified classrooms. Replace VCT flooring in 5th grade wing.	15 15	Maintenance Maintenance	Bid	35,000 25,000		13,019	- 13,019	- Complete	of new carpet due to excessive wear due to traffic and age. Replace old tile not replaced in renovation
Bwood	Replace two (2) 300-ton York chillers (HVAC)	20	Maintenance	Bid	420,000		217,863	217,863	(0) Complete	20 yr. old chillers (1992)
Rasco	Replace two (2) 150-ton chillers and cooling towers.	20	Maintenance	Bid	285,000		295,449	295,449	0 Complete	17 yr. old chillers (1995)
Beutel Ogg	Replace 155-ton York chiller and cooling tower. Replace 155-ton York chiller and cooling tower.	20	Maintenance Maintenance	Bid Bid	130,000 130,000		110,028 105,419	110,028 105,419	0 Complete (0) Complete	19 yr. old chiller (1993) 20 yr. old chiller (1992)
Lanier	Replace 150-ton chiller and cooling tower.	20	Maintenance	Coop/ Emergency	125,000		110,799	110,799	0 Complete	17 yr. old chiller (1995)
Griffith	Replace two (2) 100-ton York chillers. Replace 150-ton York chiller.	20	Maintenance Maintenance	Bid	120,000 90,000		108,922	108,922	- Complete	22 yr. old chillers (1990) 17 yr. old chiller (1995). This chiller was relocated from old Freeport Int.
Long CIS	Replace Cooling Tower	20	Maintenance	_	-		200,000	179,615	20,386	
Fleming Roberts	Replace cafeteria a/c Replace cafeteria a/c.	10	Maintenance Maintenance	Coop Coop	65,000 65,000		16,124 24,940	16,124 24,940	- Complete - Complete	Two package units in are frequently in need of repair resulting in unreliable operation Units are severely rusted and there are water leaks into cafeteria when raining
Roberts Long	Install new cooling tower and drive. Install new boiler.	20 20	Maintenance Maintenance		45,000 20,000		45,000	-	45,000	Chiller was replace five years ago however the cooling tower needs to be replaced Reached life cycle (1989) - units in are frequently in need of repair resulting in unreliable operation
Robers SFA	Install new boiler. Install new boiler	20 20	Maintenance Maintenance	Coop	20,000 20,000		- 11,350	- 11,350	Replaced before bond passed due to failure. Complete	Reached life cycle (1996) - units in are frequently in need of repair resulting in unreliable operation Reached life cycle (1989) - units in are frequently in need of repair resulting in unreliable operation
Ogg	Install new boiler	20	Maintenance	Соор	15,000		14,124			Reached life cycle (1995) - units in are frequently in need of repair resulting in unreliable operation
Bport	Replace field house HVAC with new package units.	10	Maintenance	Соор	50,000		30,465	30,465	- Complete	Reached life cycle - units in are frequently in need of repair resulting in unreliable operation
Bport Admin Bldg	Replace 3 Cooling Towers Install new A/C units.	20 10	Maintenance Maintenance	Bid	25,000		331,361 16,015	331,360 16,015	1 In progress 0 Complete	Approved Reallocated Funds from Oversight Committee and Board of Trustees Reached life cycle - Need to replace roof top units
Bport	Replace A/C unit on Dance Room.	10	Maintenance	Соор	25,000		11,839	11,839	(0) Complete	Reached life cycle -12 yrs. old - 25-ton package unit
Lighthouse LLC	Install new HVAC and ceiling in kitchen.	15	Maintenance	Соор	20,000		3,720	3,720	0 Complete	Remove ceiling, replace 7-1/2 ton split system and duct work, replace ceiling due to system not meeting demand
Polk, Fleming, Griffith, Rasco, FIS, Bwood-9th	Refurbish Existing Walk-In Freezer and Cooler (\$30k per Campus)	15	Child Nutrition	Bid	180,000		213,245	213,245	- Complete	Each walk-in is old and has different refurbishing needs. Many units need new doors and door heaters. Some units need floor and/or wall repairs. All units need new refrigeration equipment. The environment we live in takes a toll on refrigeration equipment and these units are requiring service more than what should be required to keep them running. Service is required often to avoid units going out and losing all of the food items inside
Entire District	Install Computerized Temperature Monitoring System for all Walk-In Freezers and Coolers at all Campuses		Child Nutrition	Bid	35,000		26,999	26,999	- Complete	System will monitor all walk-in units to track temperature changes and alert the CN department and maintenance of trends in temperature. This will allow units to be serviced prior to them going to out to prevent food loss. Many of the serving lines are original to the building. Most of the current lines do not have adequate heated wells. Some units run hot and have hot spots to the touch creating unsafe conditions and improper food temperature. All
Ogg, Beutel, Brannen, SFA and Polk	New Cafeteria Serving Line (\$65K per line)	20	Child Mutrition	D!4	325,000		260.465	269,465	- Complete	of the units are outdated and do not promote efficient methods of meal service and slows the speed of service to students. All of these campuses only have one serving line.
	Install New Walk-In Freezer and Cooler	20	Child Nutrition Child Nutrition	Bid	325,000		269,465	,		SFA does not have a walk in freezer and has multiple reach in units for frozen products. These units take up a lot of space and are more likely to go out than a walk-in freezer. Walk-in cooler is original to the building and does not function to full capacity often requiring maintenance assistance to keep it running.
SFA Bwood	Install new grease trap.	25 25	Maintenance		15,000		111,924 21,607	111,924 21,607	- Complete - Complete	Too small for the size of school; currently 500 gal., proposed 2000 gal.
Beutel	Install new grease trap.	25	Maintenance	1	10,000 10,000			-	Re-allocate due to 2014 Bond Re-allocate due to 2014 Bond	Original to building, cracked and leaking. City inspector recommended replacing. Original to building in need of replacement (1952)
Long Fleming	Install new grease trap. Install new grease trap.	25 25	Maintenance		10,000				- Re-allocate due to 2014 Bond	Grease trap is original to old Freeport Intermediate

						Safety &					
Facility Impacted	Bond Item	Useful Life	Department	Purchasing Method	Original Budget	Security (7.3.18)	Amended Budget	Actual Costs 8/31/18	Balance	Status	Notes (Item Details)
Roberts	Install new grease trap.	25	Maintenance		10,000		-	-	-	Re-allocate due to 2014 Bond	Original to building, in need of replacement
	Install new grease trap. Plumbing 1st - 2nd grade wing.	25 25	Maintenance Maintenance		10,000 120,000		6,250	+		Complete Re-allocate due to 2014 Bond	Original to building, in need of replacement (1952) Original galvanized piping (1942); continual leaks and low water pressure
<u> </u>		25	Maintenance		120,000		-	-	-	Tre-allocate due to 2014 Dolld	
Bwood	Install new exterior doors throughout campus.	25	Maintenance		125,000		125,000	54,582	70,418	In progress	Doors are severely worn due to very high usage and do not close properly creating safety and efficiency issues. Helping keep fleet in good and clean condition given the coastal environment. Reinstallation of a bus wash would lead to the coastal environment.
											cost effective over time as well as helping to prevent worker comp claims and help staying compliant to EPA
Transportation Facility	Automatic Bus Wash	10	Transportation		25,000		23,190	23,190	-	Complete	standards.
		6 yr. rotation									In an effort to protect the District's facilities from the elements, a comprehensive paint rotation plan for the District is
Entire District	Paint rehabilitation	cycle	Maintenance		2,400,000		938,764	273,347	665,417	Re-allocate a portion due to 2014 Bond	being reviewed for implementation. This amount would cover 6 years worth of paint assuming a 12 year rotation.
	Replace roof on athletic areas: gym, dressing rooms,										
Bwood	pool athletic field house, Slade field house.	20	Maintenance		570,000		1,128,040	1,128,040		Complete	21 yr. old roof out of warranty (1991); Other areas of building are still under warranty.
	Replace roof on entire building. Replace roof on entire building.	20	Maintenance Maintenance		535,000 445,000		527,110 445,000	506,147 318,900		Sustantially Complete In progress	22 yr. old roof out of warranty 21 yr. old roof out of warranty (1991)
Polk	Replace roof on entire building	20	Maintenance		435,000		322,074	322,074	-	Complete	20 yr. old roof out of warranty (1992)
· ·	Replace roof on original building	20	Maintenance		360,000		147,900	144,391	3,509	Re-allocate due to 2014 Bond	23 yr. old roof out of warranty; warranty expired on current roof, which was installed in 1989
	Replace roof on practice gyms, pool, and black box theatre.	20	Maintenance		335,000		365,140	365,140	_	Complete	Out of warranty (1988); Other areas of building are still under warranty due to replacement during 2002 bond program.
	Replace roof on front of building and Tally Bldg.	20	Maintenance	Bid	240,000		237,814	237,814		Complete	22 yr. old roof out of warranty (1990)
	Replace roof on 5th grade wing. Replace roof on entire building.	20	Maintenance Maintenance	Bid	230,000 225,000		255,011 221,492	226,575 221,492		Sustantially Complete Complete	18 yr. old roof out of warranty (1994) 22 yr. old roof out of warranty (1990)
CIS	Replace roof on 2nd gym.	20	Maintenance	2.0	95,000		90,660	90,660		Complete	new roof needed to protect playing surface
	Replace roof on 2nd gym. Replace roof on shop	20	Maintenance	Bid	95,000		84,660 25,182	84,660 25,182		Complete Complete	new roof needed to protect playing surface. metal roof is severely rusted
maintenance raciiity	TOPIGOO TOOT OIT OITOP	20	Maintenance	Diu	30,000		25,162	20,102	(0)	Complete	Roof leaks in many places in the shop creating an unsafe working environment for the mechanics that deal with
Transportation Cha-	Panair / Panlaca roof	20	Trongeria	D:-I	20.000		50.045	50.047		Complete	heavy machinery. Leaks do not help with the condition of equipment in shop. Ventilation from roof needs to be
	Repair / Replace roof Sub-total Renovations	20	Transportation	Bid	60,000 9,630,000	19,275	53,947 - 8,313,487	53,947 7,331,017	982,470	Complete	replaced to help with extreme heat and working conditions within the non air-conditioned shop.
	0.51-10				. , , , , , , , , , , , , , , , , , , ,	, - 1	, , ,				
	Safety/Security			ı							District wide implementation of new security cameras. The current system in place is not reliable. It unnecessarily
											utilizes network bandwidth that could be better devoted to the instructional needs of our classrooms. Current
Entire District	Security Cameras (Analog to DVR)	7	Technology	Bid	950,000	185,600	1,235,507	1,212,976	22 531	Complete	cameras have poor video quality. In addition many campuses have no security cameras and the ones that do have minimal coverage.
	Other Safety & Security Equipment	<u>'</u>	· comicing	Diu	300,000	108,922	108,922	60,902	48,020	Odinpicto	Metal Detectors, Radios, Guns and Gun Safes for Police Officer
Entire District	Bogan stand alone intercom system	15	Safety and Security	Bid	780,000		794,397	770,826	22 574	Complete, Balance for Major Components	Controls intercom, bells, clocks. There is a need for reliable paging system for crisis/emergency situations for communication.
Entire District	bogan stand alone intercom system	15	Administrative	Diu	780,000		794,397	770,020	23,371	Compete, Balance for Major Components	communication.
All 19 campuses	Security Vestibule Entrances	30	Services Administrative	Bid	760,000	181,258	757,773	772,655	(14,882)	Substantially Complete	Secure campus entrances by forcing visitors to go to office upon entering campuses
At designated campuses	Security Fences Around Playgrounds and Other	15	Services	Bid	500,000	524,000.00	850,089	702,242	147,847	Ongoing	Chain link fencing around playgrounds to prevent access and increase security.
						·					
Beutel, Roberts, Brannen, Ney, Fleming, Long,											
Griffith, Ogg, Lanier.											
Rasco, Brazoswood, Austin, Polk, Lighthouse,			Administrative								
	Keyless Entrances	15	Services	Bid	187,500		324,175	274,175	50,000	Complete	Keyless entrances prevent open access to campus and increase security.
											Cameras allow drivers to focus on their primary responsibility of driving their passengers to and from school safely. Holds all Transportation staff and passengers accountable for their behavior as well as provides documentation of
All 19 campuses	Bus Video Cameras	7	Technology		100,000		91,394	91,394	0	Complete	inappropriate or unsafe behavior.
Entire District	Intercom Station-Reception Area	15	Administrative Services		F7 000	31,000	24.000		24.000		Secure campuses front entrances by having office unlock outside door to visitors electronically.
	40-ft. trailer man-lift	15 10	Maintenance	Quotes	57,000 25,000	31,000	31,000 23,095	23,095	31,000	Complete	To repair security lighting without having to rent equipment - efficiency
	Sub-total Safety/Security				3,359,500	1,030,780	- 4,216,352	3,908,265	308,087	·	
	Equipment										
Entire District	New service vehicles	7	Maintenance	Соор	125,000		213,621	211,902		Complete	to replace five aging service vehicles
Bport Entire District	CTE Ag Truck Exmark mowers	7 5	Transportation Maintenance	Coop Coop	25,000		32,795 48,656	28,787 47,312	4,008 1,343	Complete	supply grounds crews with three new mowers
		<u> </u>	Walltellarioe	Осор	20,000		40,000	47,012	1,040	5 vehicles purchased and ordered 2 more expeditions, 1	eappy greatise create man arrest mention
	District Vehicles (10) Sub-total Equipment	10	Transportation		300,000 450,000		300,000 - 595,072		12,832 19,903	Explorer and 2 Chevy Malibus	
	Oub-total Equipment				450,000		- 393,072	373,103	19,903		
	Extra-Curricular										
Bwood, Bport, CIS, FIS,											
	Instrument Replacement, Pianos	20	Admin Services	Bid	2,000,000		2,000,000	1,918,556	,	Annually purchasing instruments	Band and Orchestra Instruments are worn due to age and can not be repaired.
Bport, Bwood Austin, Beutel, Brannen,	Uniforms	5	Admin Services	Coop	175,000		167,141	167,141	-	Complete	Marching Band uniforms fabric is threadbare and unrepairable
Fleming, Griffith, Long,	L										
	Refurbish playground slabs and tracks, replace playground equipment	20	Admin Services	Interlocal Agreement	175,000		281,962	281,962		Complete	Playground equipment aging and unsafe. Slabs and tracks cracked due to age and/or drought.
Bport	Resurface track at Hopper Field.	10	Maintenance	Bid	150,000		1,093,598	1,091,727		Complete	insufficient for competition
	Resurface track at Slade Field.	10	Maintenance	Bid	150,000		354,596	352,856		Complete	insufficient for competition
	Refurbish swimming pool. Refurbish swimming pool.	15 15	Maintenance Maintenance	Bid Bid	120,000 110,000		588,064 313,193	588,064 313,193		Complete Complete	replaster, install new ceiling and new heater replaster; install new ceiling
CIS	Replace tennis courts	10	Maintenance		80,000		80,000	80,000	-	,	Asphalt court has many large cracks needs to be concrete and resurfacing
LJI	Resurface tennis courts Sub-total Extra-Curricular	10	Maintenance	<u> </u>	15,000 2,975,000		17,249 - 4,895,803	17,249 4,810,747		Complete	Court surface is worn off
<u> </u>			<u> </u>	<u> </u>	2,57,5,000			7,010,141	00,000		
Polk	Grounds [Replace sidewalk in front of school.	25	Maintananas	Ouetee	10,000		5,000	5,000		Complete	Sidewalk is broken and separated and the seams create a tripping hazard
FOIK	Replace sidewalk in front of school.	25	Maintenance	Quotes	10,000		5,900	5,900	-	Complete	Sidewalk is broken and separated and the seams deate a tripping nazard
											Transportation sees an average of 7 - 8 "reported" on lot accidents due to limited parking space increasing out of
											pocket expenses for repair and creating cosmetic blemishes on BISD school property not helping with district's perception. Some buses are parked in unsecured areas providing opportunities of vandalism or terroristic acts due
											to limited parking. Due to limited parking employees have to park in the grass creating damage to school property
	Expand bus parking and security fencing / Expand employee parking	20	Transportation	Bid	270,000		576,081	576,081	(0)	Complete	as well as creating possible problems for personal vehicles. Personal vehicles have had to be pulled out of mud ar employees have to walk through it. Also does not help with perception to the public.
anoportation r ability	Sub-total Grounds	20	гтапаропаdOH	DIU	280,000		- 581,981	581,981	(0)		5
	Contingency Road Total				35,770	(1,200,704)	20,241		20,241		
	Bond Total ERATE Revenue Total				-		(1,551,791)	39,198,431 (1,551,791)	2,653,360		
		_		ı —	40 200 000			, , , ,			
	Grand Total			l	40,300,000		- 40,300,000	37,646,640 93.42%			